

MIRANDA HOUSE
UNIVERSITY OF DELHI


Date: 21.03.2022


Notice Inviting Quotation

Sealed quotation an invited from the civil working contractors of the College/ CPWD/ Delhi University.
"Repair work in Old Balcony class room 216,218."

Publishing Date	21/03/2022 at 1:00 P.M.
Estimated Cost	37860/-
Quotation Fee	200/- In favour of Principal, Miranda House University of Delhi.
Completion Time	25 Days
Quotation Submission Date	4/04/2022 at 4.00pm
Quotation Opening Time	5/04/2022 at 3.00pm

- Bids will be opened as per date/time on mentioned above.
- Bidder will down load the Quotation from the college website.
- The above Quotation should reach Miranda House College Office by hand on or before 04/04/2022 up to 4:00 p.m.
- The tender fee is non- Refundable.
- The unit rate for any items should be Quotation inclusive of GST.
- For general rules and directive condition of Contract, the tender shall refer to "CPWD General Condition of Contract – 2014". Except for exception mentioned in this document, which will form a part of the Agreement will up to date correction slips.


Offg. Principal


21/03/2022

QUOTATION

Name of work: Repair work in old Balcony class room 216,218.					
S.no	Items	Qty	Unit	Rate	Amount
1	13.2 15 mm cement plaster on the rough side of single or half brick wall of mix : 13.2.1 1:4 (1 cement: 4 fine sand).	12	sqm		
2	13.81 Distemping with 1st quality acrylic distemper, having VOC (Volatile Organic Compound) content less than 50 grams/ litre, of approved brand and manufacture, including applying additional coats wherever required, to achieve even shade and colour. 13.81.2 Two coats.	210	sqm		
3	13.91 Removing dry or oil bound distemper, water proofing cement paint and the like by scrapping, sand papering and preparing the surface smooth including necessary repairs to scratches etc. complete.	170	sqm		
4	Providing and applying white cement based putty of average thickness 1 mm, of approved brand and manufacturer, over the plastered wall surface to prepare the surface even and smooth complete. sqm 115.15	60	sqm		
5	Dismantaling of false ceiling.	45	sqm		
6	Removal of malba at site.	1	job		
				Total	